




Form Mould Services cc.

Phone: (011)953-3947/59
 Fax: (011)953-4994
 Email:sales@fms-sa.co.za

P.O. Box 5533
 West Krugersdorp
 1742

24 Carter Street
 Delporton
 Krugersdorp

Socket Head Cap Screws



Order Code.	d	b	D	k	s	L	Order Code.	d	b	D	k	s	L
SHCS M6 x 12	M6	18	10	6	4	12	SHCS M12 x 30	M12	28	18	12	10	30
SHCS M6 x 16						16	SHCS M12 x 35						35
SHCS M6 x 25						25	SHCS M12 x 40						40
SHCS M6 x 30						30	SHCS M12 x 50						50
SHCS M6 x 50						50	SHCS M12 x 60						60
SHCS M6 x 70						70	SHCS M12 x 70						70
							SHCS M12 x 80						80
SHCS M8 x 16	M8	22	13	8	6	16	SHCS M12 x 90						90
SHCS M8 x 20						20	SHCS M12 x 100						100
SHCS M8 x 25						25	SHCS M12 x 110						110
SHCS M8 x 30						30	SHCS M12 x 120						120
SHCS M8 x 35						35	SHCS M12 x 130						130
SHCS M8 x 50						50	SHCS M12 x 140						140
SHCS M8 x 60						60	SHCS M12 x 150						150
SHCS M8 x 70						70	SHCS M12 x 160						160
SHCS M8 x 80						80	SHCS M12 x 180						180
SHCS M8 x 90						90	SHCS M12 x 200						200
SHCS M8 x 100						100							
SHCS M8 x 110						110	SHCS M16 x 30	M16	38	24	16	14	30
							SHCS M16 x 35						35
SHCS M10 x 25	M10	25	16	10	8	25	SHCS M16 x 40						40
SHCS M10 x 30						30	SHCS M16 x 50						50
SHCS M10 x 35						35	SHCS M16 x 60						60
SHCS M10 x 40						40	SHCS M16 x 70						70
SHCS M10 x 50						50	SHCS M16 x 80						80
SHCS M10 x 60						60	SHCS M16 x 90						90
SHCS M10 x 70						70	SHCS M16 x 100						100
SHCS M10 x 80						80	SHCS M16 x 110						110
SHCS M10 x 90						90	SHCS M16 x 120						120
SHCS M10 x 100						100	SHCS M16 x 130						130
SHCS M10 x 110						110	SHCS M16 x 140						140
SHCS M10 x 120						120	SHCS M16 x 150						150
SHCS M10 x 130						130	SHCS M16 x 160						160
SHCS M10 x 140						140	SHCS M16 x 180						180
SHCS M10 x 150						150	SHCS M16 x 200						200
							SHCS M16 x 220						220
							SHCS M16 x 240						240